

Fig. 1

BEST AVAILABLE COPY




Fig. 2




Fig. 3




Fig. 4






Fig. 5

6/88





FEUILLE DE REMDI ACEMENT

48.10




Fig. 8




Fig. 9

10/508986 PCT/CH 03/00225 28. April 2003 (28. D4. 03)




Fig. 10

29




Fig. 11




Fig. 12




Fig. 13

## FEUILLE DE REMPLACEMENT




Fig. 14

15 / 88






Fig. 15



FEUILLE DE REMPLACEMENT

17 / 88



FEUILLE DE REMPLACEMENT





Fig. 18



Light but no sound No light no sound (Sleep...)

Light and sound

Fig. 19

10/508986 PCT/CH 03/00225 28. April 2003 (28. 04. 03)




Fig. 20

The Wall Control





Fig. 21



FEUILLE DE REMPLACEMENT




Fig. 23




Fig. 24

25/88




Fig. 25

## FEUILLE DE REMPLACEMENT

25/88




Fig. 25

FELIII F DE DEMBI ACEMENT







Fig. 26



FEUILLE DE REMPLACEMENT



FEUILLE DE REMPLACEMENT



FEUILLE DE REMPLACEMENT




Fig. 30




Fig. 31

## FEUILLE DE REMPLACEMENT




Fig. 32




Fig. 33






Fig. 34




FEUILLE DE REMPLACEMENT


· · · (3) ·



FEUILLE DE REMPLACEMENT



## FEUILLE DE REMPLACEMENT



FEUILLE DE REMPLACEMENT




Fig. 39

# FEUILLE DE REMPLACEMENT




Fig. 40




Fig. 41




Fig. 42




Fig. 43

### FEUILLE DE REMPLACEMENT




Fig. 44




Fig. 45





Fig. 46

47 / 88







Fig. 48



FEUILLE DE REMPLACEMENT




Fig. 50




Fig. 51




Fig. 52




Fig. 53




Fig. 54




Fig. 55

PCT/CH 03 / 00225 28. April 2003 (28.04.03)

105




Fig. 57




Fig. 58




Fig. 59





Fig. 60

· 10.



115

Fig. 61




Fig. 62




Fig. 63




Fig. 64




Fig. 65




Fig. 66

#### FEUILLE DE REMPLACEMENT




Fig. 67




Fig. 68




Fig. 69




Fig. 70

#### FEUILLE DE REMPLACEMENT

71 / 88




Fig. 71




Fig. 72

73 / 88




Fig. 73

74 / 88

The second secon

....




Fig. 74




Fig. 75

76 / 88




Fig. 76




Fig. 77




Fig.78




Fig. 79




Fig. 80




Fig. 81




Fig. 82




Fig. 83




Fig. 84





Fig. 85

86 / 88



**FEUILLE DE REMPLACEMENT** 

· Washington




Fig. 87

PCT/CH03/00225




Fig. 88

## This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

☐ BLACK BORDERS
$\square$ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
☐ GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
Потнер.

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.